442d FIGHTER WING INSTRUCTION 91-201 17 June 1998







COMPLIANCE WITH THIS PUBLICATION IS MANDATORY

NOTICE: This publication is available digitally on the HQ AFRC WWW site at: http://www.afrc.af.mil and the AFRCEPL (CD-ROM) published monthly.

OPR: 442 LG/LGQ (CMSgt Ray D. Strong)

Supersedes 442 LG OI 91-2, 5 October 1995

Certified by: 442 LG/CC (Colonel John S. Hansen)

Pages: 3

Distribution: F

This instruction implements Air Force Policy Directive (AFPD) 91-2, *Safety Programs*. It establishes procedures for the safe operation of hangar doors at Whiteman AFB MO. These procedures apply to all personnel assigned to the 442d Logistics Group and 442d Operations Group.

SUMMARY OF REVISIONS

This revision changes series number and title; and updates language, format and directives. Changes the responsibility of all assigned from 303 FS/MA to 442 OG (paragraph 1); removes the reference to the Operator (paragraph 2.6.). A (|) indicates revisions from the previous edition.

1. Responsibilities. It is the responsibility of all assigned 442 OG and 442 LG supervisors and applicable maintenance personnel to ensure the compliance of this instruction.

2. Procedures for Electrically/Mechanically Operated Hangar Doors:

- 2.1. Only qualified personnel identified by their shop/section supervisor will be authorized to operate hangar doors. Shop/section supervisors will keep their flight chief/section supervisor informed of personnel changes.
- 2.2. Operators will be thoroughly familiar with operating instructions and precautions necessary for safe operation of hangar doors. A training course outline will be maintained in training management. Training will be documented in Core Automated Maintenance System (CAMS).
- 2.3. Written operator procedures will be posted next to operating controls. Luminescent or reflective directional arrows will be placed adjacent to each operating switch and on horizontal sliding doors to indicate the direction of travel.

I

- 2.4. Operators will perform a visual check of the area, including door tracks, prior to activation of any of the door switches. WARNING: UNDER NO CIRCUMSTANCES WILL HANGAR DOORS BE OPENED TO A WIDTH OF LESS THAN TEN FEET.
- 2.5. Operators will immediately notify Maintenance Control Function (MCF) of any discrepancies found during operation of hangar doors.
- 2.6. MCF will expeditiously notify the facility manager who will initiate a work order for repair.

CHARLES E. STENNER, JR., Colonel, USAFR Commander

Attachment 1

GLOSSARY OF REFERENCES AND SUPPORTING INFORMATION

References

AFOSHSTD 91-100--Aircraft Flight Line – Ground Operations and Activities AFPD 91-2--Safety Programs